

CONTRACT NO. 
 F.A.P. RTE.
 SECTION
 COUNTY SHEET SHEETS
 NO.

 781
 1YRS, 2ZRS-1
 CRAWFORD
 378
 191
STA. TO STA. FED. ROAD DIST. NO. ILLINOIS FED. AID PROJECT



WEST WALL



EAST WALL

The quantities shown are for estimating purposes only. The actual area to be repaired will be determined by the Engineer at the time of construction. Actual repair locations shall be shown on the "As Built" plans.

## <u>LEGEND</u>



- Structural Repair of Concrete (Depth Equal to or Less than 125mm)

sq. m. - Square Meter

## BILL OF MATERIAL - BOX CULVERT NO. 11

	Unit	Total	
MX033694	Structural Repair of Concrete	sq. m.	1.9
	(Depth Equal to or Less than 125mm)		

Quantity increased by 20% to account for deterioration since field inspection.

SHEET S10 OF 19

REVISIONS								٦٣
NAME	DATE	ILLIN	OIS DEP	ARTMENT	OF TRAI	NSPO	RTATION	9803
			BOX CL	JLVERT	EXTEN	ISIO	NS	9
								2
		CONCRETE REPAIR DETAILS					ΙZ	
		вох	CULV.	NO. 11,	STA.	7+4	421.533	- 1
		SCALE	NONE		DRAWN	ВҮ	MLB	
		DATE	DECEMBER	10, 2006	CHECKE	D BY	MTH	

LIN ENGINEERING, LTD., 210 WEST CHESTNUT, CHATHAM, IL 62629 (217)-483-4168